UNIFORM HAZARDOUS WASTE MANIFEST C.A. D. O. B. 46 J. 5.1. 1.0. 1.0. 1.0. 1.0. 1.0. 1.0. 1.0	Manif 45 9 Docume	est nt No.	2. Pi				e shaded a by Federal
A Generator's Name and Mailing Address McDonner Nouglas Afreraft Co. 19503 S. Normandie Avenue			A. Stat	e Manifest 8		ent Numb 76	907
Torrance, CA 90502 4. Generator's Phone 213) 533-6677 K. L. Anderson 722	M/S C6-	10		e Generato A H Q		0,0,	5 ₁ 6 ₁ 9
	ID Number			e Transpon sporter's P		(2)	73 944 31268
	ID Number			e Transport sporter's P			
9. Designated Facility Name and Site Address 10. US EPA I Chem Tech Systems, Inc.	I I I I		G. Sta	e Facility's ムガハ	ARA	101-3	3.48
3650 E. 26th St.	un io io ic	10 11	H. Fac	llity's Phone	טיט. 268-	-3387	,
Vernon, CA 90023 C.A.4T.10.18.10 11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Numb		12. Conti	ainers Type	13. Tot Quai	al	14. Unit Wt/Vol	Wa
* Waste corrosive liquid, n.o.s., Corrosive, N	15.75	NO.	туре			W17 VOI	State
(D002) DOT E-7476-		10 11	TIT	<u> </u>	lac	G	EPA/Othe
b.							EPA/Oth
c. **		11_		1.1.1			State
		11	L	11	LL		EPA/Oth
d.							EPA/Oth
·			 1.2 20 No. 666 St. 	a como a como en la como de la co	- TORKE (S.A.)	**************************************	
J. Additional Descriptions for Materials Listed Above Waste rinse water with a Ph=2			K. Ha a.	ndling Code	es for W	Vastes L b. d.	isted Abov
	PROFIL HAULER	E #T-	а.	ndling Code	es for W	b.	Listed Abov
Waste rinse water with a Ph=2 15. Special Handling Instructions and Additional Information Guide #60. Use gloves, goggles Respirator. Tank #255 16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this con and are classified, packed, marked, and labeled, and are in all respects in propenational government regulations. If I am a large quantity generator, I certify that I have a program in place to reduct to be economically practicable and that I have selected the practicable method of present and future threat to human health and the environment; OR, if I am a small generation and select the best waste management method that is available to method.	HAULER assignment are full ar condition for to the volume as of treatment, sen	lly and arransport	a. c253 -76 courately highly y of was disposed	described vay accordi	above ng to ap	by proppplicable de degree e to me	er shipping e internatio e I have de which minir
Haste rinse water with a Ph=2 15. Special Handling Instructions and Additional Information Guide #60. Use gloves, goggles Respirator. Tank #255 16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this con and are classified, packed, marked, and labeled, and are in all respects in propenational government regulations. If I am a large quantity generator, I certify that I have a program in place to reduct to be economically practicable and that I have selected the practicable method opresent and future threat to human health and the environment, OR, if I am a smagemeration and select the best waste management method that is available to method. Printed/Typed Name Printed/Typed Name Signature	HAULER assignment are full ar condition for to the volume as of treatment, sen	lly and arransport	a. c253 -76 courately highly y of was disposed	described vay accordi	above ng to ap	by proppplicable de degree e to me	er shipping e internatio e I have de which minir inimize my
Waste rinse water with a Ph=2 15. Special Handling Instructions and Additional Information Guide #60. Use gloves, goggles Respirator. Tank #255 16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this con and are classified, packed, marked, and labeled, and are in all respects in propenational government regulations. If I am a large quantity generator, I certify that I have a program in place to reduct to be economically practicable and that I have selected the practicable method of present and future threat to human health and the environment; OR, if I am a smg generation and select the best waste management method that is available to method. Printed/Typed Name	HAULER assignment are full ar condition for to the volume as of treatment, sen	lly and arransport	a. c253 -76 courately highly y of was disposed	described vay accordi	above ng to ap	by proppplicable de degree e to me	er shipping e internatio e I have de which minir inimize my
Haste rinse water with a Ph=2 15. Special Handling Instructions and Additional Information Guide #60. Use gloves, goggles Respirator. Tank #255 16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this con and are classified, packed, marked, and labeled, and are in all respects in propenational government regulations. If I am a large quantity generator, I certify that I have a program in place to reduct to be economically practicable and that I have selected the practicable method opresent and future threat to human health and the environment, OR, if I am a smageneration and select the best waste management method that is available to method. Printed/Typed Name Signature Printed/Typed Name Signature 18. Transporter 1 Acknowledgement of Receipt of Materials	HAULER SITE Insignment are furer condition for the condition for	lly and arransport	a. c253 -76 courately highly y of was disposed	described vay accordi	above ng to ap	by proppplicable de degree e to me	er shipping e internatio e I have de which minir nimize my
15. Special Handling Instructions and Additional Information Guide #60. Use gloves, goggles Respirator. Tank #255 16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this con and are classified, packed, marked, and labeled, and are in all respects in propenational government regulations. If I am a large quantity generator, I certify that I have a program in place to reduct to be economically practicable and that I have selected the practicable method present and future threat to human health and the environment; OR, if I am a smigneration and select the best waste management method that is available to method/Typed Name Printed/Typed Name Signature 17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name Signature Signature Signature Signature Signature Signature Signature Signature Signature Signature	HAULER SITE Insignment are furer condition for the condition for	lly and arransport	a. c253 -76 courately highly y of was disposed	described vay accordi	above ng to ap	by proppplicable de degree e to me	er shipping e internatio e I have de which minir inimize my Month Q Z 1 Month
Haste rinse water with a Ph=2 15. Special Handling Instructions and Additional Information Guide #60. Use gloves, goggles Respirator. Tank #255 16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this con and are classified, packed, marked, and labeled, and are in all respects in propenational government regulations. If I am a large quantity generator, I certify that I have a program in place to reduct to be economically practicable and that I have selected the practicable method opresent and future threat to human health and the environment, OR, if I am a smageneration and select the best waste management method that is available to method. Printed/Typed Name Signature Printed/Typed Name Signature 18. Transporter 1 Acknowledgement of Receipt of Materials	HAULER SITE Insignment are furer condition for the condition for	lly and arransport	a. c253 -76 courately highly y of was disposed	described vay accordi	above ng to ap	by proppplicable de degree e to me	er shipping e internatio e I have de which minir inimize my Month Q Z 1 Month

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name

19. Discrepancy Indication Space

89476907 CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852:7550

NSE

SPILL, CALL THE NATIONAL

EMERGENCY OR

A

QF.

CASE

A

Do Not Write Below This Line

Signature

DHS 8022 A (1/88) EPA 8700-22 (Rev. 9-88) Previous editions are obsolete.

YELLOW: GENERATOR RETAINS

Month

Day

Year